



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

## MGRRE\_PureOilScoutTickets\_Dow Marshall Brine - Greendale Group\_59\_None

MGRRE  
*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

### WMU ScholarWorks Citation

MGRRE, "MGRRE\_PureOilScoutTickets\_Dow Marshall Brine - Greendale Group\_59\_None" (2021). *Legacy Scout Tickets from Pure Oil Company*. 5149.  
<https://scholarworks.wmich.edu/pure/5149>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

**MGRRE\_PureOilScoutTickets\_Dow Marshall Brine - Greendale Group\_59\_None**

API None

Permit Number None

Lease Name Dow Marshall Brine - Greendale Group

Well Number 59

County Midland

Township 14N

Range 02W

Section 15

2021 DEQ or Pure co\_name Dow Chemical Company

Pure Number 39

Latitude 43.600767469

Longitude -84.539793872

## THE PURE OIL COMPANY

## LOCATION REPORT

No. **39**DATE **Dec 13 1928**STATE **Mich** COUNTY **Midland** DIST. **Emendable** SEC. **15** TOWN **14N** RANGE **2W**WELL No. **59** (SERIAL No. **39**) FARM **Geo. Bigelow** ACRESNAME OF STREAM OR WATERS **Chippewa River** QUADRANGLEOPERATOR **Dow Chemical Co** MAP **Pure Oil Trup** **4 1/2 mi.**

Feet from North Line of Farm

" " East " " "

" " South " " "

" " West " " "

Feet from North Line of Section

" " East " " "

" " South " " "

" " West " " "

## LEGEND

O LOCATION

① RIG

⊕ DRILLING

⊗ GAS WELL

● OIL WELL

⊙ SMALL OIL WELL

⊙ DRY HOLE

⊙ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

⊙ ABANDONED GAS WELL

⊙ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.



REMARKS:

SIGNED

Superintendent or Foreman.





